

- 1. Assemble shower screen complete with front to back bracing bar.
- 2. Assemble side panel ~ do not fit bracing bar at this stage.
- 3. Measure the internal distance between side panel glass & front to back bracing bar (X).
- 4. Carefully cut & deburr side panel bracing bar to X—6mm.
- 5. At 'factory cut' end of bar, fit joining bracket to bar end & mark hole positions. Remove bracket & drill 2x dia 4mm hole through top surface of bar only. Refit bracket & affix with (3,5x12) CSK screw.
- 6. Using bracket as a guide, mark & drill dia 2,5 \sim 3mm hole through top surface of main bracing bar & affix with (3,5x12) CSK screw.
- 7. For Hinge Door bracing bar tee joint—determine tee bar position, & follow steps 5 & 6 only.

